CARR-1258

1925

Maintenance Shop

Public

Springfield Hospital Center

Sykesville

The Maintenance Shop is a one story building constructed of stucco over cast concrete. The building measures eight bays long and four bays deep. A flat roof covers the building.

Maryland Historical Trust State Historic Sites Inventory Form

Survey No. CARR-1258

Magi No. 07/2584739

DOE __yes __no

1. Nan	ne (indicate p	referred name)		· .
historic Gã	arage/Mechanical St	Oreroom		
and/or common	Maintenance Shop			
2. Loc	ation Springfie	ld Hospital Conto		
street & number		id nospital Center		
	esville			not for publication
		vicinity of	congressional district	6
state Maryl 3. Clas		county	Carroll	
	sification			
Category district building(s) structure site object	Ownership	Status X occupied unoccupied work in progress Accessible yes: restricted yes: unrestricted no	Present Use agriculture commercial educational entertainment government industrial military	museum park private residence religious scientific transportation x other: Hospital
4. Own	er of Prope	rty (give names a	nd mailing addresses	
name	Department of He	alth and Mental Hyg	iene	va .
street & number	201 West Preston			.: 301-225-6816
city, town	Baltimore	state	- 1	
5. Loca	tion of Lega	al Description		land 21201
		County Courthouse		
street & number		th Court Street	Annex, Rm G-8	liber
		in Court Street		folio
6. Repr	The second secon		state ^{Ma}	ryland 21157
o. nepr	esentation	in Existing	Historical Surve	ys
tle				
late			federal state	county local
lepository for surv	vey records		Jaie	county local
ity, town	·			
			state	

7. Description

Survey No. CARR-1258

endition _ excellent deteriorated _ good ruins _ fair unexposed	Check one unaltered _X altered	Check one X original site moved date	of move	
--	--------------------------------	--	---------	--

Prepare both a summary paragraph and a general description of the resource and its various elements as it exists today.

The Maintenance Shop is a one story, stucco building measuring eight bays long and four bays deep. Located just north of the Powerhouse, the main facade looks west. Because the building rests on the side a hill, the basement level is visible on the north, south and east facades. A flat roof covers the structure.

The fenestration pattern on the west wall has been altered. The ghosts of the larger, original windows are visible. The austral windows display a brick sill, metal surrounds and single sash. A product of the 1920's, austral windows were often used in public buildings for increased ventilation. The remaining fenestration on the other walls consists of large, multipaned pivot windows with metal surrounds and mullions. The pivot windows are slightly recessed and lack any sill or lintel.

The main entrance on the west wall has also been altered to a set of doors. wooden doors are adorned by a large surround. A raised string course runs above the doorway and could be considered as a lintel for the door. The stucco wall bows outward slightly to form the cornice. A short parapet rises from the flat roof and frames the building.

The east wall repeats the large metal windows. In addition, the ground level exhibits two large openings for retractable garage doors. The wooden doors operate on metal tracks. A common pier divides the openings. The area functions as an auto shop. A single door appears on the northern end of the wall. It displays a large wooden transom. The opening contains a door within a door and both open outward away from the building.

-eriod	Areas of Significance—C — archeology-prehistoric — agriculture — x architecture — art — commerce — communications	check and justify below community planning conservation economics education engineering exploration/settleme industry invention	landscape arc law literature military music	hitecture religion science sculpture x social/ humanitarian theater hment transportation other (specify)
Specific dates	1925	Builder/Architect Spr	ringfield State	Hospital
a	nd/or	B <u>x</u> CD	_EFG	
Leve	1 of Significance: _	_national <u>x</u> state	local	

8. Significance

Prepare both a summary paragraph of significance and a general statement of history and support.

The Board of Managers of Springfield State Hospital adopted a resolution on May 1, 1925 which authorized the construction of a new garage. The cost was not to exceed \$6000. One of the people responsible for the garage was Senator Wolfe. A plaque recognizing his contribution hangs on the west wall of the building. The resolution also authorized money for the construction of a refrigeration shop. These expenditures acknowledged the growing needs of the hospital in other areas outside the realm of patient care and treatment. The construction of the garage, identified today as the Maintenance Shop, permitted the hospital to complete one more task on the campus, namely automotive repair. This perpetuated the idea of self-sufficiency of the hospital.

The construction material of stucco over cast concrete was a common choice for "industrial" buildings on the hospital grounds in the 1920's. The barns and the refrigeration shop are other examples on the grounds. The choice of construction material helped to identify the function of the building. All of the patient buildings were constructed with brick so the stucco and concrete indicated a building with a support function.

9. Major Bibliographical References

Survey No. CARR-1258

10. Geo	graphical Data
Quadrangle name	do NOT complete UTM references
A Zone Easting	Northing Zone Easting Northing
C	
Verbal boundary	description and justification (1944 1945) (1944 1945) (1944 1945) (1944 1945)
List all states ar state	d counties for properties overlapping state or county boundaries code county code
state	code county code
11. Forr	n Prepared By
name/title	Lauren L. Bowlin
organization	Office of Planning, DHMH date 6/86
street & number	201 West Preston Street telephone 301-225-6816
city or town	Baltimore state Maryland 21201

The Maryland Historic Sites Inventory was officially created by an Act of the Maryland Legislature to be found in the Annotated Code of Maryland, Article 41, Section 181 KA, 1974 supplement.

The survey and inventory are being prepared for information and record purposes only and do not constitute any infringement of individual property rights.

return to:

Maryland Historical Trust

Shaw House

21 State Circle

Annapolis, Maryland 21401

(301) 269-2438



CARR-1258
Maintenance Shop
Springfield Hospital Center
Sykesville, Maryland
Don Jewell, 6/86
Negatives at MHT
West and North Face



CARR-1258
Maintenance Shop
Springfield Hospital Center
Sykesville, Maryland
Don Jewell, 6/86
Negatives at MHT
East and South